Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	(analyz\$3 or evaluat\$3) near5 radiant\$1 near5 energy\$1 near5 flame\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:07
L2	1671	(analyz\$3 or evaluat\$3) near5 (photodiode\$1 or thermopile\$1 or pyro-electric\$1 or passive\$1 near5 infrared\$1 or flame\$1 or radiant\$1 near5 energy\$1) near5 flame\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:24
L3	1182	I2 and (heat\$1 or thermal\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:10
L4	67	I3 and (adjust\$3 or check\$1 or alter\$1 or chang\$3) near5 (sensitivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:11
L5	5	l4 and (false\$1 near5 alarm\$1 or nuisance\$1 near5 alarm\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:11
L6	0	(analyz\$3 or evaluat\$3) near5 flame\$1 same (thermal\$1 or heat\$1) same (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:26
L7	0	(analyz\$3 or evaluat\$3) near5 (fire\$1 or flame\$1) same (thermal\$1 or heat\$1) same (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:27
L8	8	(analyz\$3 or evaluat\$3) near5 (fire\$1 or flame\$1) same (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:27

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	(analyz\$3 or evaluat\$3) near5 radiant\$1 near5 energy\$1 near5 flame\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:07
L2	1671	(analyz\$3 or evaluat\$3) near5 (photodiode\$1 or thermopile\$1 or pyro-electric\$1 or passive\$1 near5 infrared\$1 or flame\$1 or radiant\$1 near5 energy\$1) near5 flame\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:24
L3	1182	I2 and (heat\$1 or thermal\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:10
L4	<b>67</b> <sub>.</sub>	I3 and (adjust\$3 or check\$1 or alter\$1 or chang\$3) near5 (sensitivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:11
L5	5	I4 and (false\$1 near5 alarm\$1 or nuisance\$1 near5 alarm\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:11
L6	0	(analyz\$3 or evaluat\$3) near5 flame\$1 same (thermal\$1 or heat\$1) same (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	·OR	OFF '	2005/04/27 11:26
L7	0	(analyz\$3 or evaluat\$3) near5 (fire\$1 or flame\$1) same (thermal\$1 or heat\$1) same (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:27
L8	8.	(analyz\$3 or evaluat\$3) near5 (fire\$1 or flame\$1) same (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:34
L9	3	(fire\$1 or flame\$1) near5 (analyz\$3 or evaluat\$3) with (chang\$3 or adjust\$3 or check\$3 or alter\$3) near5 (sensivity\$1 or level\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/04/27 11:35